PAPERS LAID ON THE TABLE.

Postponed Questions and Answers.

Sri Kadidal MANJAPPA (Minister for Revenue and Public Works).—I beg to lay on the Table of the House replies to 47 questions remaining for answer from the last Session and replies to 6 questions which were promised in the last Session. The Questions and Answers will be printed in to-day's proceedings.

Major and Minor Tanks in Nagamangala Taluk.

Q.—1. **Sri M. SANKAR LINGE GOWDA** (Nagamangala).—

Will the Government be pleased to state :—

the names of major and minor tanks situated in the villages of Nagamangala taluk with the area under *atchkat* and the assessment of each tank with the remarks 'restored or unrestored', and also the condition of each tank, and the amount spent from the year 1881 to the end of the year 1951-52?

A.—**Sri KADIDAL MANJAPPA** (Minister for Revenue and Public Works).—

Statement given below. Regarding the amount spent from the year 1881 to end of 1951-52, the figures are only approximate as could be obtained from the available records. Tanks with an atchkat of less than 5 acres are not taken into account.

The column "condition of tank" could not be filled in the case of a few tanks, as information in respect of them is not readily available.

Sl. No.	Name of village	Name of tank	Atchkat	Assessment	Restored or unrestored	Condition of tank	Amount spent from 1881 to end of 1951 52	Remarks
		Major Tanks		Rs.			Rs.	
1	Bagamangala ...	Naganakere Tank ...	400	400 Water rate.	Restored in 1936-7 ...	Good ..	31,500	.....
2	Kelagere ...	Tank ...	78 Wet 22 Garden.	370 ...	do 1895 ...	Under restoration ...	14,799	.....
3	Melhalli ...	Tank ...	100		1934-35 ...	Fair ; in need of maintenance works.	16 572	.....
4	Nagamangala ...	Ammanakatte ...	81	386-4 0 ..		Fair ...	3,418	.....
5	Do ...	Sulekere ..	380	2010 ...	Restored in 1988 97 ...	Go d ..	5 ,000	.....
6	Do ...	Singarasinakere ...	106	428 ...	do 1987-92 ...	Good but maintenance neglected.	32,000	.....
7	Do ...	Hirekere ...	328	1652 ...	do 1918-22 ...	Fair ; maintenance to bund necessary.	54,000	.....
8	Anchechittanahalli ...	Tank ...	120	... ..	do 1936 37 ...	Good ...	59 400	.....
9	(Mulakatte) Madalahalli.	Tank ...	135	.. ..	do 1936-87 ...	Fair ...	32,430	.....
10	Bindenahalli ...	Tank ...	336	1562 ...	do 1891-96 ...	Good but bed silted up.	32,165	.....
11	Devalapura ...	Urumundinakere ...	110	492 ...	do 1388 ...	Fair ; requires maintenance and some improvement works.	7,730	.....
12	Dondemadahalli ...	Kodiagikefe (Hosak re).	80 Ac.	... ...	Being restored from 1942-43 ..	Good ...	26,480	.....
13	Hiduva ...	Tank ...	575	2299 Water rate.	do 1936 37 ...	Good ...	1,25,000	.....
14	Kotebetta ...	Palkere ...	473	2555 ...	do 1902 ...	Good, bund maintenance neglected by r iya's.	1,00,000	.....
15	(Garukahalli) or Ragurampura.	Tank ...	174	1025 ...	do 1899-1902 ...	Good, bund in need of maintenanc and R. Chal, to be improved.	16,983	.....
16	Somanahalli ...	Tank ...	99	323 Water rate.	do 1889 ...	Good, channel tampered by raiyats.	12,000	.....
17	Bhusandra ...	Tank ...	114	460 ...	do 1898 ...	Bed badly silted up ...	30,091	.....
18	Chikkayagati ...	Hutchikere ...	401	... ..	do 1935-36 ...	Good, Rt. Bank Chl. to be improved.	1,18,000	.....
19	Manchipatna ...	Tank ...	229	... ..	do 1927-28 ...	Fair, capacity being increased.	65,000	.....
20	Doddajataka ...	Dasanakere ...	125	508 ...	do 1884-98 ...	Fair, requires improvements.	17,000	.....
21	Bellur ...	Tank ...	615	3315 ...	do 1899 ...	Fair, in need of general repairs.	37,500	.....

Sl. No.	Name of village	Name of tank	Atchkat	Assessment	Restored or unrestored	Condition of tanks	Amount spent from 1881 to end of 1951-52	Remarks
		Major Tanks—		Rs.			Rs.	
22	Honnenahalli ...	Tank ...	192	742 ...	Being Restored from 1889.	Fair, small improvements.	52,980	.....
23	Thigalanahalli ...	Tank ...	113	502 ...	do 1891 ...	Do repairs ...	46,2 0	.....
24	Arani ...	Tank ...	76	322 ...	do 1989-96 ...	Good ...	7,500	.....
25	Mudigere ...	Tank ...	70	... ...	do 1938-39 ...	Good ..	31,000	.....
26	Koppa ...	Tank ...	138	722 ...	do 1898 ...	Good ...	13,730	.....
27	Belagumba Kelakere ...		103	499 ...	do 1896 ...	Fair, in need of certain repairs.	12,500	.....
28	Ramachandra Agrahar.	Tank ...	101	440 ...	do 1894 ...	Fair, bed silted up ...	25,200	.....
29	Honnavara ..	H rekere ...	255	1049 ...	do 1902 ...	Fair ...	31,500	.....
30	Do ...	Kalkere ...	79-13	342/8 ...	.....	Fair, Maintenance work badly neglected.	5,522	Since 1939.
31	Bindiganavale ...	Kadagikere ...	596	2205 ...	do 1896 ...	Good ..	28,000	.....
32	Dadaga ...	Tank ...	468	2228 ...	do 1889 ...	Bad ...	56,500	.....
33	Heragenahalli ...	Tank ...	555	2393 ..	do 1888 ...	Good, requires minor repairs.	40,000	.....
34	Bommanahalli ...	Tank ...	128-19	402 Water rate.	do 1935-36 ...	Good ...	28,026	.....
35	Jodi Alpahalli ...	Hutchikere ...	(195)	... ...	Under restoration ...	.....	9,000	.....
36	Bidarkere ...	Hirekere ...	(144)	... ...	Newly sanctioned for restoration.	.....	...	.....
		MINOR TANKS (With atchkat of 5 acres and more).		Rs.			Rs.	
1	Kargere ...	Tank ...	45	225 ..	Restored in 1946 ...	Good, Sluice requires new plug and rod.	12,274	...
2	Byadarahalli ...	Hosakere ...	22	... ...	Being restored from 1949	... ...	8,591	Restoration work under progress.
3	Deereswarapura ...	Tank ...	20	... ..	Do 1944	Good Irrigation Chl. requires repairs.	16,530	Do
4	Peduvalaneralekere (Kurubarahalli). ...	Tank ...	20	... ...	Do 1945	Good ...	10,644	Do
5	Yagat Halli ...	Shanbhoganakatte ...	20-5	... ...	Do 1945-46	Fair ...	2,161	...
6	Tuppadamadu .	Surankere ...	17	... ...	Do 1944-45	Fair, maintenance to bund neglected.	4,500	Feeder channel has been proposed.
7	Jodi Hulekere ...	Tank ...	14	48 ...	Not restored ...	... ...	...	...
8	Malrajpur ...	Hosakere ...	10	22 ...	Restored 1944-45 ...	Fair natural weir washed off & requires to be replaced by masonry weir.	1,527	...

	Hullenahalli ...	Urumundinakere ...	47	226 ...	Do 1906 ...	Fair ..	15,123	Estimate for increasing capacity is under operation.
10	Maddenahatti ...	Tank ...	57	... ...	Do 1907 ...	Fair ...	9,50	..
11	Mai arapatna ...	Do ...	55	173 ...	... ...	Bad ...	918	...
12	Th:mallanaikanahalli	Do ...	37	116 ..	Do 1927-28 ...	Good, weir requires prospective works.	5,10	...
13	Sampanahalli ...	Do ...	30	... ...	Do 1934-35 ...	Fair ...	7,987	...
14	Dandiganahalli ...	Do ..	25	1.5 ...	... ...	Bad ...	90	To be taken up for restoration.
15	Hullenahalli ...	Challere ...	25	... ...	Being restored 1946-47...	Good ...	7,112	Estt. for increasing capacity under operation.
16	Devaramallanaikanahalli.	Tank ...	24	91 ...	Restored ...	Fair ...	1,350	...
17	Ankanhalli ...	Do ..	21	73 ...	... ...	Good. bund requires maintenance.	120	Further figures not available.
18	Jakkanahalli tank ... (Kempegowdanakere)	Do ..	16	52 ...	Not restored ...	Bad ...	...	Not available
19	Doddaupalla ...	Do ...	15	55 ...	Do ...	Good, Chal. to be improved.	1,672	Do
20	Thubinakere ...	Tank ...	13	43 ...	Restored 1889 ...	Fair, bund needs earthwork.	1,672	...
21	Thibarahalli Sannikatte.	Do ...	10	34 ...	Do ...	Do do ...	465	...
22	Chikkanahalli tank ...	Do ...	9	26 ...	Not restored ...	Fair ..	...	Not available
23	Devaramadahallikere ...	Do ...	7	24 ...	Do ...	Good ...	6 0	...
24	Madhalli Madhallikere...	Do ...	65	264 ...	Restored ...	Fair, maintanance neglected.	3,050	...
25	Chinya tank ...	Do ...	41	... ...	Restored 1943 ..	Fair ...	18,187	Two new sluices and channels proposed.
26	Manhalli Mathikere ...	Do ...	89	121 ..	Restored ...	Bad ...	7,627	...
27	Bommadihalli ...	Jaramakatte ...	38	123 ...	Do ...	Fair, bed badly silted up.	...	Not available
28	Thonginahalga ...	Do ...	33	44 ...	Do 1946-47 ...	Fair ...	6,260	...
29	Maradabuvanahalli tank (Hoskote).	Do ...	13	65 ...	Being restored from 1946-7.	Fair, W.W. & Aquaduct needs protective works	4,205	...
30	Bommanaikanahalli ...	Uramundinakere ...	20	... ...	Restored 1924-25 ...	Fair bund requires maintenance & sluice repairs.	2,740	...
31	Gangavadi ..	Koppadakere ...	15	56 ...	Not restored ...	Fair ..	..	...
32	Jutanahalli ..	Hongekatte ..	13	... ...	Restored 1946-47 ...	Fair, there is a leak in in the bund to be closed	7,746	Not available
33	Hindasahalli ...	Mogivanakatte ...	13	34 ...	Not restored ...	... ...	...	...
34	Malasandara ...	Uramundinakere ..	12	41 ...	Do ...	Fair ..	...	...
35	Sukadhare ..	Chikkanakatte ..	9	27 ..	Do ...	... ...	...	...
36	Masanaikanahalli ...	Hulikatte ...	9	25 ...	Do ..	... ..	...	...
37	Kalligudi ..	Ajalacharikatte ..	8	25 ...	Do ...	... ...	...	...
38	Kalienahalli ...	(Gumaladakatte) ..	8	20 ..	Do ...	Fair, irrigation Chal bad.	...	...

L.A.

10

Sl. No.	Name of Village	Name of Tank	Atchkat	Assessment	Restored or unrestored	Condition of Tank	Amount spent from 1881 to end of 1951-52	Remarks
							Rs.	
39	Handenahalli katte ...	(Gomaladakatte) ...	6	20 ...	Not restored ...	Fair ..	...	...
40	Medderalli Thimmana-katte	Do ..	5	12 ...	Do ...	... ...	...	...
41	Lakkenahalli tank ...	Do	66	... ...	Restored 1941-42 ...	Good, requires earth work to bund.	26,720	...
42	Nelligere ...	Hatna tank ...	64	... ...	Do 1934-35 ..	Fair, bund weak & do	16,200	...
43	Bettadakote ...	Tank ...	55	... ...	Do 1927-28 ...	Fair, requires petty repairs	9,820	...
44	Chunchanahalli ...	Aiynakatte ...	47	142 ...	Do ...	Fair, requires sml Impts.	1,279	Estt. sanctioned works to be taken up.
45	Nagathihalli ...	Gowdanakere ...	47	207 ...	Restored ...	Good, requires maintenance bund.	2,203	...
46	Karijeerahalli ...	Tank ...	80	Water rate ...	Restored 1950-51 ...	Good ...	85,585	...
47	Nagathihalli ...	Punalgere ...	60	... ...	Under restoration ..	Fair ...	18 187	...
48	Thonavinakere ...	Tank ..	28	... ...	Restored 1935-47 ...	Heavily silted up otherwise fair.	8,004	...
49	Yalachikere ...	Dalavoykatte Tank ...	25	67 ...	Not restored .	... ...	...	Not available
50	Byalakere ...	Tank ...	19	91 ...	Restored in 1927-28 ...	Bad ...	5,872	...
51	Nanchinkote ...	Tank ..	20	72 ...	Not restored ...	Good ...		...
52	Hampapura ...	Naganakere Tank ...	110	... ...	Under restoration 1946-47	Fair ...	9 269	...
53	Basavanadra ...	Tank ...	20	75 ...	Restored ...	Good ...	2,438	...
54	Byalakere ..	Chikkanakatte ...	6	... ...	do 1941-42 ..	... ..	1 240	...
55	Siddapur Gowdanakatte	do ...	10	220 ...	do 1950-51 ...	Good ...	3 000	...
56	Honnavara Hulikere ...	do ...	43	16 ...	do 1878 ...	Fair, maintanence neglected.	2,684	...
57	Cholenahalli Tank ...	do ...	40	... ...	do 1944-45 ...	Fair maintenance neglected.	18,500	...
58	Sathenahalli ..	Nakkanakere ...	52	Water rate 260	do 1944-43 ...	Fair, leaks in bund to be closed.	21,410	...
59	Kadabahalli ...	Urumandinakere ...	38	183 ...	do 1878 ...	Fair, bund to be strengthened.	4,0 0	...
60	Jakkundi ...	Tank ...	25	... ...	do 1947-23 ...	... ...	2,7 4	...
61	Kadabahalli ...	Channegowdankatte...	13	73 ...	do 1876 ...	Good, feeder encriached by raiyats.	3,730	...
62	Voddarahalli ...	Hunaikatte ...	16	64 ...	do 1947-47 ...	... ...	11,800	...
63	Bettadahalli ...	Malledevarakatte ...	14	85 ...	do 1941 ...	... ...	4,021	...

64	Jodi daddahala	...	Tank	...	8	27	...	Not restored	...	Bad	...	Nil	...
65	Jammahalli	...	Kalegowdanakatte	...	14	36	...	do	...	...	...	...	Not available
66	Hanumanahalli	...	Aladakatte	...	10	52	...	Under restoration	...	...	..	5,380	...
67	Koravangundi Hunisakatte.		do	...	9	...	...	do	...	...	...	...	do
68	Jadharayakanahalli	...	Karalukatte	...	7	19	...	Not restored	...	Fair	...	...	do
69	Gunjanhalli	...	Settarakatte	...	6	...	...	do	...	Good	...		do
70	Dadanudi e	...	Gundalakere	...	40	...	...	Restored 1942-43	...	Good	...	28,200	...
71	Viddarahalli	...	Taluk	...	24	...	...	do 1943-44	...	Bad	...	8,93	...
72	Tholali	...	do	...	80	...	...	do	...	...	...	25,000	...
73	Jodi Hatti	..	do	...	...	...	...	do	...	...	...	1,000	...
74	Kachenahalli	...	do	...	20	Acres Garden+ 30 wet.		do	...	...	...	...	...
75	Ambalajerahalli	...	do	...	32	Acres 192 water ra e.		do	...	...	...	...	...
76	Gollarahalli	...	do	...	19	Acres 114 water rate		do	...	...	...	...	Recently sanctioned for restoration.